


TYPICAL WIRING SCHEMATIC

With IEC Direct-On-Line (DOL) Option



LEGEND

- M = CONTACTOR
- CB = CIRCUIT BREAKER
- CCH = CRANKCASE HEATER
- FLA = FULL LOAD AMPERE
- FU = FUSE
- Hp = MOTOR HORSE POWER
- HLP = HIGH-LOW PRESSURE SWITCH
- LRA = LOCKED ROTOR AMPERE
- MCA = MINIMUM CIRCUIT AMPERE
- MFS = MAXIMUM FUSE SIZE
- MP = MOTOR PROTECTOR
- MRA = MAXIMUM RUNNING AMPERE
- NRA = NOMINAL RUNNING AMPERE
- TR = TIMER DELAY RELAY
- OL = OVERLOAD PROTECTOR
- RC = RUN CAPACITOR
- RLA = RATED LOAD AMPERE
- SW = SWITCH
- TB = TERMINAL BLOCK
- TH = THERMOSTAT
- * = FIELD SUPPLY
- ▲ = MANUAL RESET
- = FIELD WIRING
- = FACTORY WIRING

